Oil Field Environmental Incident Summary

Incident:	20180107134	852 No	<i>tice:</i> 1/7/2018	13:48 Oc o	curred: 1/6/2018	22:20		
Responsible Party:		HESS BAKKEN INVESTMENTS II, LLC						
Well Operator:		HESS BAKKEN INVESTMENTS II, LLC						
Well Name:		EN-LEO E- 154-94-2423H-4						
Field Name:		ALKALI CREEK						
Well File #:		27674						
Facility ID #:								
County:		MOUNTRAIL						
Twp Rng Sec Qtr:		154 94 24						
Location Description:		EN Leo E 2423 pad H4-12, NE corner of location (small grass fire from flare, both on / off location) estimated burned area of 326 Sq. Ft on location and 68 Sq. Ft off location.						
Submitted By:		Troy Brunsell						
Received By:								
Contact Info:		Troy Brunsell						
		1501 MCKINNEY						
		HOUSTON TX 77010						
Affected Medium:		Topsoil						
General Land Use:		Other - Described Above						
Near. Occupied Bldg:		1 Mile						
Nearest Water Well:		1 Mile						
Type of Incident:		Fire						
Release Contained:		No						
Reported to NRC:		No						
	Spilled	Units	Recovered	Units	Followup	Units		
Oil								
Brine								
Other	5.2	Gallons			5.2	gallons		

Other	5.2	Gallons		5.2	gallo
Oth Rel. Contaminant:		Condensate	,		
Date Inspected:					
Clean Up Concluded:		5/16/2018			
Written Report Recd:		5/30/2018			
D () D					

Risk Evaluation:

No immediate risk to report at this time.

Areal Extent:

NE corner of location 326 Sq. Ft on location / 68 Sq. Ft off location.

Potential Env. Impacts:

NE corner of location burned the grass in an area estimated at 326 Sq. Ft on location / 68 Sq. Ft off location.

Action Taken/Planned:

Grass fire area was walked down to ensure it was completely extinguished, production equipment / pressures checked and monitored.

Wastes Disposal Location:

No waste to dispose of at this time.

Other Agencies Involved:

Updates

Date: 1/8/2018 Status: Reviewed - Follow-up Required

No Further Action:

Author: Crowdus, Kory

Notes:

Condensate release and fire off location. Follow-up is required.

Updated Volumes and Contaminant None at the time of this update

Date: 1/12/2018 Status: Inspection

No Further Action: 🗸

No Further Action:

Author: Schiermeister, Robin

Notes:

Arrived on site at 11:20 on 1-10-2018. It was windy with wind speeds 5-10 miles per hour and temperatures near 5 degrees Fahrenheit. The fire went north off the well pad until it reached an access road to the landowner's field to the north. The contamination appears to have been cleaned up and stockpiled on site. An inspection will be needed in the summer to check for vegetation regrowth.

Updated Volumes and Contaminant None at the time of this update

Date: 6/6/2019 Status: Inspection

Author: O'Gorman, Brian

Notes:

Arrived on location at 9:52. 71 degrees F, Sunny, South wind 5-15 mph. Observed the area of concern and took photos. It appeared that the vegetation north of the flare had returned to its original growth stand. Did not notice any damaged and/or unhealthy plants. No further follow-up needed at this time. Photos added to the incident folder.

Updated Volumes and Contaminant None at the time of this update