Oil Field Environmental Incident Summary

Incident: 20180112150351 Notice: 1/12/2018 15:03 Occurred: 1/12/2018 01:00

Responsible Party: CONDOR PETROLEUM, INC.
Well Operator: CONDOR PETROLEUM, INC.

Well Name: TANGSRUD 12-1

Field Name: HAYLAND Well File #: 10210

Facility ID #:

County: DIVIDE

Twp Rng Sec Qtr: 160 96 12 NE NW

Location Description:

Submitted By: JoAnn Klevenberg

Received By:

Contact Info: JoAnn Klevenberg

216 16TH STREET SUITE 1750

DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 1320 Feet Nearest Water Well: 1320 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 75 Barrels 70 barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 6/13/2018
Written Report Recd: 6/22/2018

Risk Evaluation:

NONE

Areal Extent:

Potential Env. Impacts:

gravel inside dike will be washed with fresh water if needed when weather permits

Action Taken/Planned:

Contained within the dike, load line split approximately 75 bbls of sw was released from tanks and contained within the dike, will pulled up sw and haul to disposal (waiting for a vac truck to get to location). Will clean up dike if needed when weather permits.

Wastes Disposal Location:

Will put down our disposal

Other Agencies Involved:

Updates

Date: 1/16/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Martin, Russell

Notes:

Release, due to valve/piping connection leak, remained on location, according to the report. NDIC

retains oversight.

Updated Volumes and Contaminant None at the time of this update