

# *Oil Field Environmental Incident Summary*

**Incident:** 20180113223942      **Notice:** 1/13/2018    22:39      **Occurred:** 1/13/2018    04:30

**Responsible Party:** HENRY HILL OIL SERVICES, LLC

**Well Operator:** HENRY HILL OIL SERVICES, LLC

**Well Name:** DVORAK-SEIDL 1-27-3C

**Field Name:** LITTLE KNIFE

**Well File #:** 8277

**Facility ID #:**

**County:** DUNN

**Twp Rng Sec Qtr:** 145 97 27

**Location Description:**

**Submitted By:** Matt Azure

**Received By:**

**Contact Info:** Matthew Azure  
120 26TH STREET EAST  
SUITE 200  
WILLISTON ND 58801

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 2 Mile

**Nearest Water Well:** 2 Mile

**Type of Incident:** Equipment Failure

**Release Contained:** Yes - On Facility Site

**Reported to NRC:** Yes

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	14	Barrels	14	Barrels		

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

NA

**Areal Extent:**

NA

**Potential Env. Impacts:**

water is contained in the site containment.

**Action Taken/Planned:**

valve on line closed, and joint replaced. keep watch on equipment and try to notice wear and replace. all water was inside the containment, and will be sucked up and pumped down at site.

**Wastes Disposal Location:**

on site after it is faced up.

**Other Agencies Involved:**

NDIC Nicole

## **Updates**

---

**Date:** 1/16/2018      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

Release, due to equipment failure, remained on location, according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update