

Oil Field Environmental Incident Summary

Incident: 20180115130514 **Notice:** 1/15/2018 13:05 **Occurred:** 1/13/2018 1145

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: RUSCH B 1

Field Name: SHERWOOD

Well File #: 3580

Facility ID #:

County: RENVILLE

Twp Rng Sec Qtr: 164 85 25

Location Description:

Submitted By: Scott Hunskor

Received By:

Contact Info: Scott Hunskor
777 MAIN STREET
SUITE 800
FORT WORTH TX 76102

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	8	Barrels	8	Barrels	8	barrels
Brine	2	Barrels	2	Barrels	2	barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 1/17/2018

Written Report Recd: 2/7/2018

Risk Evaluation:

none

Areal Extent:

Potential Env. Impacts:

none

Action Taken/Planned:

Shut well in, tighten stuffing box. Clean up around well, check out pressure switch and replace if necessary

Wastes Disposal Location:

Clean Harbors.

Other Agencies Involved:

Updates

Date: 1/16/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release, due to stuffing box leak, remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update