

Oil Field Environmental Incident Summary

Incident: 20180119110948 **Notice:** 1/19/2018 11:09 **Occurred:** 1/19/2018 07:54

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: Dickinson Lodgepole Central Site

Field Name: DICKINSON

Well File #:

Facility ID #: 413447-01

County: STARK

Twp Rng Sec Qtr: 140 96 32 SW NW

Location Description: NWSE 31-140-96 -- *SPILL WAS ON #74 site to the north of the manifold.

Submitted By: Beki Sample

Received By:

Contact Info: Beki Sample
4901 LBJ FREEWAY, STE 300
DALLAS TX 75244

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 1320 Feet

Nearest Water Well: 300 Feet

Type of Incident: Pipeline Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels	10	Barrels	10	barrels
Other						

Oth Rel. Contaminant: N/A

Date Inspected:

Clean Up Concluded: 2/7/2018

Written Report Recd: 12/10/2018

Risk Evaluation:
N/A

Areal Extent:
N/A

Potential Env. Impacts:
N/A

Action Taken/Planned:
Wells were shut in and water flow was stopped. A vac truck was dispatched to suck up water from the ground. A crew was dispatched to replace the pipe with the hole in it. Contaminated soil will be replaced

Wastes Disposal Location:
Water will be put back into storage tanks. Contaminated soil will be taken to R360 Chimney Butte facility

Other Agencies Involved:

Updates

Date: 1/19/2018 ***Status:*** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: Martin, Russell

Notes:

Release, due to pipeline leak, remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update