

Oil Field Environmental Incident Summary

Incident: 20180309122920 **Notice:** 3/9/2018 12:29 **Occurred:** 3/9/2018 07:00

Responsible Party: WPX ENERGY WILLISTON, LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: ARIKARA 15-22HA

Field Name: REUNION BAY

Well File #: 33619

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 150 93 15

Location Description:

Submitted By: Robert Raup

Received By:

Contact Info: Robert Raup
3500 One Williams Center- MD38
TULSA OK 74172

Affected Medium: Topsoil

General Land Use: Pasture

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Gallons				

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

There are no immediate risks associated with this incident.

Areal Extent:

The impacted area is being surveyed, but a light misting did travel to the west of the pad.

Potential Env. Impacts:

Potential environmental impacts are minimal. The misting appears to have rested on top of snow, making the cleanup easier to manage. A cleanup crew is already on location removing impacted snow. WPX will ensure the cleanup is sufficient by sourcing a third party consultant to inspect and sample the location.

Action Taken/Planned:

Contractors on location did a great job of shutting in the equipment upon the incident, which greatly minimized the impact of the release. Cleanup contractors are on location and will ensure that all impacted areas are remediated.

Wastes Disposal Location:

The impacted snow is being removed and will be placed in a de-watering box on location. The snow

will be melted down and hauled off with a load of production water for proper disposal.

Other Agencies Involved:

MHA Energy
TAT Environmental
BIA

Updates

Date: 3/9/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.

Updated Volumes and Contaminant None at the time of this update