Oil Field Environmental Incident Summary

Responsible Party: FUTURE ACQUISITION COMPANY, LLC **Well Operator:** FUTURE ACQUISITION COMPANY, LLC

Well Name: HECKMAN 7-6-1H

FORTUNA Well File #: 25664

Facility ID #:

County: DIVIDE
Twp Rng Sec Qtr: 162 101 7

Location Description:

Submitted By: Chris Haefele

Received By:

Contact Info: Chris Haefele

PO BOX 1129

FULSHEAR TX 77441

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 3499 Feet

Nearest Water Well:

Type of Incident: Treater Leak
Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Barrels	30	Barrels	30	barrels
Brine	50	Barrels	50	Barrels	50	barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 6/21/2018 Written Report Recd: 7/3/2018

Risk Evaluation:

No immediate risks to environment.

Areal Extent:

Potential Env. Impacts:

No potential environmental impacts. The fluid was recovered immediately

Action Taken/Planned:

Spill was contained in the dike. The well was shut down, a vaccuum truck was immediately on location to recover released fluids. Hydrovac truck in route to wash soil and clean location. Future has taken steps to replace anode protection of the treater on this and other locations. Damage was likely done during operations prior to our taking over the well. Will continue to inspect anode protection and inspect burners during routine treater maintenance.

Wastes Disposal Location:

Fluids were returned to production tanks. Any soil removed will be taken to 3 Mile Disposal facility.

Other Agencies Involved:

Updates

Date: 3/13/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release of oil and brine was contained to the well pad. NDIC

takes oversight.

Updated Volumes and Contaminant None at the time of this update