

Oil Field Environmental Incident Summary

Incident: 20180314152833 **Notice:** 3/14/2018 15:28 **Occurred:** 3/11/2018 10:30

Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Name: YOGI 14-7H-0607-15895-TF

Field Name: TEMPLE

Well File #:

Facility ID #: 126825-01

County: WILLIAMS

Twp Rng Sec Qtr: 158 95 7 SW SW

Location Description: On the well site near the flare.

Submitted By: Michael Ellis

Received By:

Contact Info: Michael Ellis
1200 17TH STREET, SUITE 2200
DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 0.8 Mile

Nearest Water Well: 0.8 Mile

Type of Incident: Fire

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other						

Oth Rel. Contaminant: Produced gas - combusted at the site.

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None

Areal Extent:

No release of fluids

Potential Env. Impacts:

None

Action Taken/Planned:

A redundant flare is being removed from the site to eliminate the fuel and ignition source.

Wastes Disposal Location:

No wastes were generated

Other Agencies Involved:

Updates

Date: 3/14/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the fire did not produce any contaminants. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update