

Oil Field Environmental Incident Summary

Incident: 20180316080607 **Notice:** 3/16/2018 08:06 **Occurred:** 3/15/2018 12:35

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC
Well Name: BEAVER LODGE-DEVONIAN UNIT D-307
Field Name: BEAVER LODGE
Well File #: 3900
Facility ID #:
County: WILLIAMS
Twp Rng Sec Qtr: 155 96 2
Location Description:
Submitted By: Alex Beach
Received By:
Contact Info: Mathew Fossen
 3015 16th Street SW, Suite 20
 Minot ND 58701

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 0.2 Mile
Nearest Water Well: 0.2 Mile
Type of Incident: Stuffing Box Leak
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	9.1	Gallons			9.1	gallons
Oth Rel. Contaminant:	Emulsion					

Date Inspected:
Clean Up Concluded: 4/5/2018
Written Report Recd: 4/16/2018

Risk Evaluation:

Hess personnel were on location, at the time of the release, and were able to isolate the release shortly after it occurred.

Areal Extent:

The light mist covered an estimated 20' by 20' area.

Potential Env. Impacts:

The mist which impacted off location, was light, and slightly discolored the top of the crusted snow. It covered an estimated 20' by 20' area. There are not any environmental impacts expected.

Action Taken/Planned:

Hess personnel were on location, and able to isolate the release shortly after it occurred. A remediation contractor was notified. The Hess Land Department was notified and will contact the landowner. The impacted snow off location will be removed. The impacted areas on location will be remediated.

Wastes Disposal Location:

All recovered waste will be disposed of at an approved waste disposal facility.

Other Agencies Involved:

Updates

Date: 3/16/2018 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Schiermeister, Robin

Notes:

Release, due to a stuffing box leak, did not remain on the well pad. An inspection will be needed to determine the extent of damage.

Updated Volumes and Contaminant None at the time of this update

Date: 4/3/2018 **Status:** Inspection **No Further Action:**

Author: Stockdill, Scott

Notes:

Arrived on location 15:17 4/3/2018.

Spray from stuffing box to NW off of well. Impacted areas have been scraped up but recent snow has obscured cleanup. GPS coordinates: 48.273137, -102.984832.

More follow-up is necessary to ensure proper cleanup.

Updated Volumes and Contaminant None at the time of this update

Date: 10/22/2018 **Status:** Inspection **No Further Action:**

Author: Schiermeister, Robin

Notes:

Arrived on site at 15:05 on 10-15-2018. It was sunny and windy. Walked around the northwest perimeter of the well pad. The vegetation in the area is green and actively growing. There is a sparse area of vegetation past this area to the north; however, it appears to be a dry creek bed. No further follow-up is necessary at this time.

Updated Volumes and Contaminant None at the time of this update