

Oil Field Environmental Incident Summary

Incident: 20180316184033 **Notice:** 3/16/2018 18:40 **Occurred:** 3/16/2018 15:09

Responsible Party: HENRY HILL OIL SERVICES, LLC

Well Operator: HENRY HILL OIL SERVICES, LLC

Well Name: SCHAEFER 1-2

Field Name: STANLEY

Well File #: 10544

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 155 91 2

Location Description:

Submitted By: Matthew Azure

Received By:

Contact Info: Matthew Azure
120 26TH STREET EAST
SUITE 200
WILLISTON ND 58801

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	12	Barrels	12	Barrels	12	barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 3/18/2018

Written Report Recd: 3/23/2018

Risk Evaluation:

na

Areal Extent:

na

Potential Env. Impacts:

na / contained in lined containment

Action Taken/Planned:

water sucked up clamp replaced

Wastes Disposal Location:

sucked up into site system.

Other Agencies Involved:

NDIC Jason Hicks

Updates

Date: 3/19/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Crowdus, Kory

Notes:

Release remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update