Oil Field Environmental Incident Summary

								~
Incident: 201805131140)47	Notice:	5/13/2018	11:40	Occurred	: 5/13/2018	8 08:00
Responsible Party:		EOG RES	OURC	ES, INC.				
Well Operator:		EOG RESOURCES, INC.						
Well Name:		BURKE 6-04H						
Field Name:		ROSS						
Well File	#:	17728						
Facility ID #:								
County:		MOUNTRAIL						
Twp Rng Sec Qtr:		155 90 4						
Location Description:		Inside of tank battery berm.						
Submitted By:		Hunter Ball						
Received By:								
Contact Info:		Danielle Dupay						
		600 17TH ST., STE 1000N						
		DENVER CO 80202						
Affected Medium:		Well/Facility Soil						
General Land Use:		Well/Facility Site						
Near. Occupied Bldg:								
Nearest	Water Well:							
Type of Incident:		Valve/Piping Connection Leak						
Release Contained:		Yes - Within Dike						
Reported to NRC:		No						
	Spilled	Units	_	Recovered	Units		Followup	Units
Oil	20	Barrels		20	Barrels		20	barrels
Brine								
Other								
	Contaminant:							
Date Inspected:		- /- / / -						
Clean Up Concluded:		7/3/2018						
Written Report Recd:		7/13/2018						
Risk Evaluation:								
None	4 4							
Areal Ext								
Potential Env. Impacts:								
None Action Takon/Plannadi								
Action Taken/Planned:								
A vac-truck was brought in an removed all standing oil. A hydro vac, will be used to remove all								

A vac-truck was brought in an removed all standing oil. A hydro vac, will be used to remove a contaminated soils tomorrow.

Wastes Disposal Location:

The oil that was sucked up, was put back into the production tanks. Any contaminated soils will be disposed of at an approved disposal.

Other Agencies Involved:

Updates

Date: 5/14/2018 Status: Reviewed - Assigned to Other Agency

No Further Action: 🗸

Author: O'Gorman, Brian

Notes:

Release, due to a valve/piping connection leak, was contained within the diking, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update