

Oil Field Environmental Incident Summary

Incident: 20180521160559 **Notice:** 5/21/2018 16:05 **Occurred:** 5/16/2018 16:48

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BLDU FF-310

Field Name: BEAVER LODGE

Well File #: 15185

Facility ID #:

County: WILLIAMS

Twp Rng Sec Qtr: 156 96 25 SE SE

Location Description:

Submitted By: Alex Beach

Received By:

Contact Info: Troy Brunsell
3015 16th Street SW, Suite 20
Minot ND 58701

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 0.5 Mile

Nearest Water Well: 0.5 Mile

Type of Incident: Pipeline Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.4	Barrels			0	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 5/22/2018

Written Report Recd: 8/31/2018

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

The release impacted an estimated 8' by 9' by 6" area, on location.

Potential Env. Impacts:

The release impacted an estimated 8' by 9' by 6" area, on location. There is no environmental risk to report at this time.

Action Taken/Planned:

The Hess Senior Reliability Operator (SRO) stopped the pumping unit and isolated the flow line. They dispatched a vacuum truck to remove the remaining oil from the flow line. A Hess Environmental, Health, and Safety (EHS) representative will contact an environmental contractor to conduct a remediation of the impacted area.

Wastes Disposal Location:

All recovered waste will be transported to an approved waste disposal facility.

Other Agencies Involved:

Updates

Date: 5/21/2018 **Status:** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update