Oil Field Environmental Incident Summary

Incident: 20180521161044 Notice: 5/21/2018 16:10 Occurred: 5/20/2018 16:30

Responsible Party: CONTINENTAL RESOURCES, INC.
Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: SYVERSON 1-1H

Field Name: EAST FORK

Well File #: 21775

Facility ID #:

County: WILLIAMS
Twp Rng Sec Qtr: 156 100 1

Location Description:

Submitted By: Cooper Fink

Received By:

Contact Info: Cooper Fink

PO BOX 268870

OKLAHOMA CITY OK 73126

Affected Medium: Topsoil

General Land Use: Pasture

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Fire Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 5/21/2018
Written Report Recd: 5/25/2018

Risk Evaluation:

None

Areal Extent:

500' x 35' area to the North

Potential Env. Impacts:

Topsoil

Action Taken/Planned:

The fire was put out using water.

Wastes Disposal Location:

N/A

Other Agencies Involved:

NDIC - Gunther Harms @ 3:45 P.M. 5/21/2018 NDDoH - Bill Suess @ 3:50 P.M. 5/21/2018

Landowner - Duane Syverson - 3:53 P.M. 5/21/2018

Updates

Date: 5/21/2018 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the fire was not contained to the well pad. Further follow-up is needed to assure no contaminants were released with fire.

Updated Volumes and Contaminant None at the time of this update

Date: 6/5/2018 Status: Inspection No Further Action: ✓

Author: Schiermeister, Robin

Notes:

Arrived on site at 15:12 on 5-31-2018. It was cloudy with temperatures in the 60s. Fire burned the grass north of the well pad, approximately 100 by 40 feet. Off pad there was no odor, just staining from the burnt material. Vegetation is starting to grow back in that area and looks healthy. No further follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update