

# Oil Field Environmental Incident Summary

**Incident:** 20180523084018      **Notice:** 5/23/2018      08:40      **Occurred:** 5/22/2018      15:30

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** TERESA D 1-10H

**Field Name:** JUNO

**Well File #:** 34767

**Facility ID #:**

**County:** DIVIDE

**Twp Rng Sec Qtr:** 162   96   10

**Location Description:** Spill was on the intersection of highway 5 and 110th Ave NW, all of spill on highway 5

**Submitted By:** Ryan Rasmussen

**Received By:**

**Contact Info:** Ryan Rasmussen  
PO BOX 268870  
OKLAHOMA CITY OK 73126

**Affected Medium:** Topsoil

**General Land Use:** Other - Described Above

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

**Oil**

**Brine**

<b>Other</b>	10	Gallons	10	Gallons	10	gallons
--------------	----	---------	----	---------	----	---------

**Oth Rel. Contaminant:** Invert drilling mud

**Date Inspected:**

**Clean Up Concluded:** 5/22/2018

**Written Report Recd:** 5/25/2018

**Risk Evaluation:**

Driving Hazard

**Areal Extent:**

10' x 50'

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

Divide County Sheriff helped diverted traffic from the right lane and spill was cleaned off the highway by a hydrovac and disposed of.

**Wastes Disposal Location:**

Secure Disposal

**Other Agencies Involved:**

Local Law Enforcement Divide County Sheriffs Office

### Updates

---

**Date:** 5/23/2018      **Status:** Reviewed - Follow-up Required      **No Further Action:** ☒

**Author:** Schiermeister, Robin

**Notes:**

Release, due to a truck overflow, was not contained. The release occurred approximately 8 miles east of Crosby on the roadway. An inspection is needed to determine the extent of damages.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 5/23/2018      **Status:** Inspection      **No Further Action:** ☒

**Author:** Stockdill, Scott

**Notes:**

Arrived on location at 5:13 5/23/2018.

No sign of contamination at the described location. Contact company regarding location. No photos taken.

More follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 8/29/2019      **Status:** Awaiting Documentation      **No Further Action:** ☒

**Author:** Suess, Bill

**Notes:**

The RP has been contacted to request verification of remediation at the site. Once the documents are reviewed the site will be revisited to assure proper revegetation.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 1/3/2020      **Status:** Correspondence - Vegetation Check      **No Further Action:** ☒

**Author:** Suess, Bill

**Notes:**

Received follow-up report from the RP. Vegetation check needed in Spring 2020.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 8/31/2020      **Status:** Inspection - No Action Required      **No Further Action:** ☒

**Author:** Suess, Bill

**Notes:**

Inspected the site on 8/27/2020. No adverse environmental impacts associated with this incident were observed. The vegetation appears healthy and consistent with the surrounding area. No further action is warranted at this time.

**Updated Volumes and Contaminant**    None at the time of this update