

Oil Field Environmental Incident Summary

Incident: 20180710102513 **Notice:** 7/10/2018 10:25 **Occurred:** 7/9/2018 21:00

Responsible Party: CONTINENTAL RESOURCES, INC.
Well Operator: CONTINENTAL RESOURCES, INC.
Well Name: HAMLET 7-2H
Field Name: HAMLET
Well File #: 23853
Facility ID #:
County: WILLIAMS
Twp Rng Sec Qtr: 159 96 2
Location Description: Crude oil misted from flare pit off location to the north west.
Submitted By: Ryan Rasmussen
Received By:
Contact Info: Ryan Rasmussen
PO BOX 268870
OKLAHOMA CITY OK 73126
Affected Medium: Topsoil
General Land Use: Pasture
Near. Occupied Bldg:
Nearest Water Well:
Type of Incident: Equipment Failure
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Gallons	5	Gallons	15	gallons
Brine						
Other						

Oth Rel. Contaminant:
Date Inspected:
Clean Up Concluded: 7/11/2018
Written Report Recd: 7/18/2018
Risk Evaluation:
N/A
Areal Extent:
150' x 90'
Potential Env. Impacts:
Topsoil
Action Taken/Planned:
Misted gravel on location will be raked and affected grass on and off location will be cut and bagged.
The bagged grass will be taken to R360 disposal.
Wastes Disposal Location:
R360 Disposal
Other Agencies Involved:
Duane Fenster Landowner 8:30
Jonathon Rumpee NDIC 10:05 (Left message)

Updates

Date: 7/10/2018 **Status:** Reviewed - Follow-up Required **No Further Action:** ☒

Author: Martin, Russell

Notes:

Release due to equipment failure, was not contained on location according to the report. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 7/10/2018 **Status:** Inspection **No Further Action:** ☒

Author: Crowdus, Kory

Notes:

On location 7/10/2018, at 4:28pm. Release impacted area off location to the North/Northwest of flare. An area approximately 40x30 yards has been mowed. Some staining remains on vegetation. Further follow-up is required to monitor vegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 9/6/2019 **Status:** Awaiting Documentation **No Further Action:** ☒

Author: Suess, Bill

Notes:

The RP has been contacted to request verification of remediation at the site. Once the documents are reviewed the site will be revisited to assure proper revegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 1/3/2020 **Status:** Correspondence - Vegetation Check **No Further Action:** ☒

Author: Suess, Bill

Notes:

Received follow-up report from the RP. Vegetation check needed in Spring 2020.

Updated Volumes and Contaminant None at the time of this update

Date: 7/23/2020 **Status:** Inspection - No Action Required **No Further Action:** ☒

Author: Suess, Bill

Notes:

Inspected the site on 7/21/2020. No adverse environmental impacts associated with this incident were observed. The vegetation appeared healthy and consistent with the surrounding area. No further action is warranted.

Updated Volumes and Contaminant None at the time of this update