

Oil Field Environmental Incident Summary

Incident: 20180907112653 **Notice:** 9/7/2018 11:26 **Occurred:** 9/7/2018 06:15

Responsible Party: WHITE ROCK OIL & GAS, LLC

Well Operator: WHITE ROCK OIL & GAS, LLC

Well Name: FEDERAL FRANKS 33 2

Field Name: WHISKEY JOE

Well File #: 7562

Facility ID #:

County: BILLINGS

Twp Rng Sec Qtr: 141 100 33

Location Description:

Submitted By: STEPHANY COOK

Received By:

Contact Info: JOHN ED WILLIMON
5810 Tennyson Pkwy
SUITE 500
DALLAS TX 75024

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine	15	Barrels	15	Barrels		
--------------	----	---------	----	---------	--	--

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Low

Areal Extent:

An area of 1.5' x 4' off-site was affected right next to the dike where the water soaked in.

Potential Env. Impacts:

Low

Action Taken/Planned:

Vac truck was on location by the time incident was called in. All 38 BBL are recovered. Contaminated soil will go to R360 facility.

Wastes Disposal Location:

R360

Other Agencies Involved:

US Forest Service

Updates

Date: 9/7/2018 **Status:** Reviewed - Follow-up Required

No Further Action: ☒

Author: Schiermeister, Robin

Notes:

Release, due to equipment failure, was not contained. An inspection will be needed to determine the extent of damage.

Updated Volumes and Contaminant None at the time of this update

Date: 9/14/2018 **Status:** Inspection

No Further Action: ☒

Author: Schiermeister, Robin

Notes:

Arrived on site at 8:33 on 9-11-2018. It was sunny with temperatures in the 70s. The release occurred south of the central tank battery. Walked along the grassland outside of the dike and saw no impacts. Probed the area with a conductivity probe; however, found readings around 247 uS. There are still some impacts onsite with the contamination being stockpiled there as well; however, on site activities are under the jurisdiction of NDIC. No further follow-up is necessary at this time.

Updated Volumes and Contaminant None at the time of this update