Oil Field Environmental Incident Summary

						-
Incident: 201809071652 Responsible Party: Well Operator: Well Name:		SCOUT ENERGY MANAGEMENT LLC SCOUT ENERGY MANAGEMENT LLC FRANKS CREEK STATE 2-14XH			Occurred: 9/7/2018	10:27
Field Name:		T. R.				
Well File #:		7538				
Facility ID #:						
County:		BILLINGS				
	g Sec Qtr:	141 101 14	SE SE			
Location Description:						
Submitted By:		Beki Sample				
Received By:						
Contact Info:		Beki Sample 4901 LBJ FREEWAY, STE 300				
		DALLAS TX 75244				
Affected Medium:		Well/Facility Soil				
General Land Use:		Well/Facility Site				
Near. Occupied Bldg:		0.3 Mile				
Nearest Water Well:		0.3 Mile				
Type of Incident:		Tank Overflow				
Release Contained:		Yes - Within Dike				
Reported to NRC:		No				
	Spilled	Units	Recovered	Units	Followup	Units
Oil	8	Barrels	8	Barrels		
Brine	7	Barrels	7	Barrels		
Other						
Oth Rel. Contaminant:						
Date Inspected:						
Clean Up Concluded:						
Written Report Recd:						
Risk Evaluation:						
N/A						
Areal Ex	tent:					
N/A						
Potentia	I Env. Impacts:					
N/A						
Action T	aken/Planned:					

Action Taken/Planned:

A vac truck was dispatched and recovered the spilled product. It was returned to the storage tank. A steam truck was sent out to steam off the tank and the vac truck recovered this contaminated water also. Contaminated rock and soil will be hauled out and disposed of and clean rock will be brought in.

Wastes Disposal Location:

Indian Hills disposal

Other Agencies Involved:

Updates

Date: 9/17/2018 Status: Reviewed - Assigned to Other Agency No Further Action: 🗸

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill remained on location within the diking. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update