

# Oil Field Environmental Incident Summary

**Incident:** 20180909154100      **Notice:** 9/9/2018      15:41      **Occurred:** 9/6/2018      15:44

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** BW-ROLFSON-151-98- 2116H-3

**Field Name:** SIVERSTON

**Well File #:** 25266

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 151 98 21

**Location Description:**

**Submitted By:** Alex Beach

**Received By:**

**Contact Info:** Troy Brunsell  
3015 16th Street SW, Suite 20  
Minot ND 58701

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 0.3 Mile

**Nearest Water Well:** 0.3 Mile

**Type of Incident:** Fire

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

The RO extinguished the fire. There is no immediate risk to report at this time.

**Areal Extent:**

**Potential Env. Impacts:**

There are no environmental impacts to report at this time.

**Action Taken/Planned:**

The RO used a portable fire extinguisher to extinguish the fire.

**Wastes Disposal Location:**

**Other Agencies Involved:**

## Updates

---

**Date:** 9/10/2018      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Release, due to a fire, was not contained, according to the report. Further follow-up needed.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/14/2018      **Status:** Inspection      **No Further Action:**

**Author:** Schiermeister, Robin

**Notes:**

Arrived on site at 16:30 on 9-10-2018. It was sunny with temperatures in the 80s. Release went west of the flare. Walked over to the area and saw that the fire continued over the hill until the access road. The vegetation in this area is burnt; however, there are no signs of contamination. A vegetation check should be done next spring.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/4/2019      **Status:** Correspondence - Vegetation Check      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Site will be inspected next inspection week.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 10/1/2019      **Status:** Inspection - No Action Required      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Observed the release location and took photos. It appeared that the vegetation in the impacted area was healthy and in accordance to the other vegetation types along the same gradient of the well pad. No further followup needed at this time. Photos added to the incident folder.

**Updated Volumes and Contaminant**    None at the time of this update