

Oil Field Environmental Incident Summary

Incident: 20180911094611 **Notice:** 9/11/2018 09:46 **Occurred:** 9/10/2018 14:30

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: SFTU 4-35

Field Name: FRYBURG

Well File #: 13311

Facility ID #:

County: BILLINGS

Twp Rng Sec Qtr: 139 101 35 NW NW

Location Description:

Submitted By: Beki Sample

Received By:

Contact Info:
 Beki Sample
 4901 LBJ FREEWAY, STE 300
 DALLAS TX 75244

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 3 Mile

Nearest Water Well: 3 Mile

Type of Incident: Tank Leak

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	100	Barrels	100	Barrels	100	barrels

Other

Oth Rel. Contaminant: N/A

Date Inspected:

Clean Up Concluded: 9/20/2018

Written Report Recd: 4/25/2019

Risk Evaluation:

N/A

Areal Extent:

2' x 5' area

Potential Env. Impacts:

N/A

Action Taken/Planned:

The spill was contained within the dike. A vac truck was dispatched and recovered the water in the dike. The water was disposed of in a disposal facility. This is an extra storage tank with heavier oil on the bottom. The tank will be cleaned out and the heavier oil will either recycled or disposed of. As this was an extra storage tank, this tank will be removed and not replaced

Wastes Disposal Location:

Indian Hills disposal

Other Agencies Involved:

US Forest Service

Updates

Date: 9/11/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to a tank leak, was contained within the diking, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update