

# Oil Field Environmental Incident Summary

**Incident:** 20190107164518      **Notice:** 1/7/2019      16:45      **Occurred:** 1/7/2019      13:00

**Responsible Party:** EQUINOR ENERGY LP

**Well Operator:** EQUINOR ENERGY LP

**Well Name:** STALLION 33-28 1H

**Field Name:** RAGGED BUTTE

**Well File #:** 21431

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 151 101 33

**Location Description:** South east corner of well pad Stallion 33-28-1H pipeline launcher

**Submitted By:** Jimmy Dickson

**Received By:**

**Contact Info:** Jimmy Dickson  
6300 BRIDGE POINT PKY, BLDG 2  
SUITE 100  
AUSTIN TX 78730

**Affected Medium:** Topsoil

**General Land Use:** Other - Described Above

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained:** No

**Reported to NRC:** No

|     | Spilled | Units   | Recovered | Units   | Followup | Units |
|-----|---------|---------|-----------|---------|----------|-------|
| Oil | 3       | Gallons | 3         | Gallons |          |       |

Brine

Other

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

30 feet to the WSW by 10 feet to the south

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

Closed valve on launcher completely as soon as the release started. Verify all valves are completely closed at future launching.

**Wastes Disposal Location:**

IHD Indian Hills Disposal

**Other Agencies Involved:**

## Updates

---

**Date:** 1/7/2019      **Status:** Reviewed - Follow-up Required

**No Further Action:** ☒

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 1/11/2019      **Status:** Inspection

**No Further Action:** ☒

**Author:** Martin, Russell

**Notes:**

1/9/2019 at 11:36, on location. Launcher is just off location (outside the wellpad perimeter berm) to the southeast. Spray went approximately southeast over some fencing and native grasses. Based on direction, further southeast is a dirt road (30th Street NW or County Road 20), but no visible staining on the road or past the road to the southeast. Visibly stained grasses have been cut, only the stubble remains. According to report contact, they are waiting for One Call to mark lines before going in and scraping the ground. Follow-up in spring/summer to confirm vegetative recovery.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 6/24/2019      **Status:** Inspection

**No Further Action:** ☒

**Author:** Biemiller, Richard

**Notes:**

Arrived on site at 17:09 on 06/19/2019. It was overcast with temperatures in the 70's. There was no evidence of staining or any obvious odor. Vegetation regrowth was near 70%. Due to these reasons, no further follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update