Oil Field Environmental Incident Summary

Incident: 20190310151448 Notice: 3/10/2019 15:14 Occurred: 3/10/2019 11:00

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: COLUMBIA 5-5H
Field Name: DOLLAR JOE

Well File #: 24006

Facility ID #:

County: WILLIAMS
Twp Rng Sec Qtr: 155 97 5

Location Description: 15' x 30' snow misting to the east

Submitted By: chansy wolff

Received By:

Contact Info: jacob renne

1459 bishop ave

OKLAHOMA CITY OK 73126

Affected Medium: Topsoil

General Land Use: Cultivated

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Other Release Contained: No Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits5Gallons5Gallons5gallons

Brine Other

Oil

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 3/11/2019 Written Report Recd: 3/15/2019

Risk Evaluation:

na

Areal Extent:

15' x 30'

Potential Env. Impacts:

topsoil

Action Taken/Planned:

all contaminated snow will be removed and disposed of

Wastes Disposal Location:

nearest disposal

Other Agencies Involved:

Updates

Date: 3/11/2019 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: Martin, Russell

Notes:

Release due to unspecified cause, was not contained on location, according to the report. Follow-up

is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 3/13/2019 Status: Inspection No Further Action: ✓

Author: Crowdus, Kory

Notes:

On location 3/13/2019, at 10:16am. Area to the east off location is mostly snow covered. Possible minor staining to the east of flare pit. Further follow-up is required to check on vegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 1/2/2020 Status: Correspondence - Vegetation Check No Further Action: ✓

Author: Suess, Bill

Notes:

Received follow-up report from the RP. Vegetation check needed in Spring 2020.

Updated Volumes and Contaminant None at the time of this update

Date: 7/23/2020 Status: Inspection - No Action Required No Further Action: ✓

Author: Suess, Bill

Notes:

Inspected the site on 7/21/2020. No adverse environmental impacts associated with this incident were observed. The vegetation appeared healthy and consistent with the surrounding area. No further action is warranted.

Updated Volumes and Contaminant None at the time of this update