

Oil Field Environmental Incident Summary

Incident: 20190516081134 **Notice:** 5/16/2019 08:11 **Occurred:** 5/15/2019 07:27

Responsible Party: Scout Energy Partners
Well Operator: SCOUT ENERGY MANAGEMENT LLC
Well Name: Fryburg-Heath-Madison-Unit H-814HR
Field Name: FRYBURG
Well File #: 5436
Facility ID #:
County: BILLINGS
Twp Rng Sec Qtr: 139 101 2 SE S2
Location Description:
Submitted By: Beki Sample
Received By:
Contact Info: Beki Sample
 4901 LBJ Freeway
 Suite 300
 Dallas TX 75244
Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 2.1 Mile
Nearest Water Well: 775 Feet
Type of Incident: Stuffing Box Leak
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Barrels	1.5	Barrels		

Brine
Other

Oth Rel. Contaminant: N/A

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None

Areal Extent:

There is a very fine mist that left location approximately 15' x 15'

Potential Env. Impacts:

None

Action Taken/Planned:

A vac truck and hot oiler were dispatched to the location and the oil was recovered along with the contaminated water used to clean the location.

Wastes Disposal Location:

Wash water and oil will be taken to public disposal

Other Agencies Involved:

Updates

Date: 5/16/2019 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 7/5/2019 **Status:** Inspection

No Further Action:

Author: Suess, Bill

Notes:

Visited the site on 7/2/2019. The impacted vegetation had been mowed and is recovering nicely. No further action is warranted. No photos taken.

Updated Volumes and Contaminant None at the time of this update