

Oil Field Environmental Incident Summary

Incident: 20190523160526 **Notice:** 5/23/2019 16:05 **Occurred:** 5/23/2019 11:07

Responsible Party: Scout Energy Management
Well Operator: SCOUT ENERGY MANAGEMENT LLC
Well Name: TRMU 22X-16H
Field Name: T. R.
Well File #: 16906
Facility ID #:
County: BILLINGS
Twp Rng Sec Qtr: 141 101 16 NW SE
Location Description:
Submitted By: Beki Sample
Received By:
Contact Info: Beki Sample
 4901 LBJ Freeway
 Suite 300
 Dallas TX 75244
Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 1.5 Mile
Nearest Water Well: 1.5 Mile
Type of Incident: Valve/Piping Connection Leak
Release Contained: Yes - On Constructed Well Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels	2.5	barrels

Brine
Other

Oth Rel. Contaminant: N/A

Date Inspected:
Clean Up Concluded: 9/23/2019
Written Report Recd: 10/14/2019

Risk Evaluation:
 None

Areal Extent:
 N/A

Potential Env. Impacts:
 There will be no environmental impacts

Action Taken/Planned:
 A vac truck was dispatched and recovered as much oil as possible. A skidsteer cleaned up the contaminated soil and it was taken to the appropriate landfill

Wastes Disposal Location:
 Indian Hills Disposal

Other Agencies Involved:

Updates

Date: 5/23/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release due to valve/piping connection leak remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update