

# *Oil Field Environmental Incident Summary*

**Incident:** 20190809124133      **Notice:** 8/9/2019      12:41      **Occurred:** 8/7/2019      20:00

**Responsible Party:** MUREX PETROLEUM CORPORATION

**Well Operator:** MUREX PETROLEUM CORPORATION

**Well Name:** HELLING 1-19

**Field Name:** PRONGHORN

**Well File #:** 11150

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 150 101 19 SE SE

**Location Description:**

**Submitted By:** William Jansky

**Received By:**

**Contact Info:** Shannon Holter  
363 N. Sam Houston Pkwy. E.  
Suite 200  
HOUSTON TX 77060

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	13	Gallons	13	Gallons		
<b>Brine</b>	6	Barrels	6	Barrels		

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Env. Impacts:**

Minimal

**Action Taken/Planned:**

The well was shut in and stuffing box rubbers replaced. Equipment brought in to scrape and excavate contaminated soil. NDIC Devin Quick notified by phone on 8/8/19 @1200PM.

**Wastes Disposal Location:**

Secure 13 mile corner

**Other Agencies Involved:**

## **Updates**

---

**Date:** 8/9/2019

**Status:** Reviewed - Assigned to Other Agency

**No Further Action:**

**Author:** Martin, Russell

**Notes:**

Release due to stuffing box leak remained on location, according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant** None at the time of this update