

Oil Field Environmental Incident Summary

Incident: 20190813163406 **Notice:** 8/13/2019 16:34 **Occurred:** 8/13/2019 09:00

Responsible Party: The 85 Disposal, Inc
Well Operator: THE 85 DISPOSAL, INC.
Well Name: HERMAN SCHMITZ 27-1
Field Name: INDIAN HILL
Well File #: 7651
Facility ID #:
County: MCKENZIE
Twp Rng Sec Qtr: 153 101 28 NE SW
Location Description: GPS 48.04705 N, 103.67637 W, Wheat Field
Submitted By: Sam Thome
Received By:
Contact Info: Chris Robinson
 423 1st Ave E
 WILLISTON ND 58801

Affected Medium: Topsoil
General Land Use: Cultivated
Near. Occupied Bldg: 2100 Feet
Nearest Water Well: 2100 Feet
Type of Incident: Pipeline Leak
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Gallons				
Brine						
Other	12	Barrels				

Oth Rel. Contaminant: Twelve barrels FW with trace hydrocarbons

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None

Areal Extent:

100' x 30'

Potential Env. Impacts:

None

Action Taken/Planned:

Line is secured and blinded on each end and contains freshwater

Wastes Disposal Location:

IHD

Other Agencies Involved:

NDDEQ

Updates

Date: 8/14/2019 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 8/28/2019 **Status:** Inspection **No Further Action:**

Author: O'Gorman, Brian

Notes:

Arrived on location at 17:52. 87 degrees F, Sunny, Southwest wind 10-20 mph. Drove to the GPS location and took photos. The GPS point was approximately 300 feet into a mature wheat field. I did not notice any equipment tracks through the wheat field and/or notice any impacted wheat. More follow-up needed. Photos added to the incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 9/3/2019 **Status:** Correspondence **No Further Action:**

Author: O'Gorman, Brian

Notes:

Spoke to the company contact via telephone at 14:50. Was informed that they had not begun work due to the landowner requesting them waiting until he harvested the wheat field. The contact insured me that the location provided on the report, via GPS was correct and they would most likely be remediating the site this week or next week. More follow-up needed.

Updated Volumes and Contaminant None at the time of this update

Date: 9/4/2019 **Status:** Inspection **No Further Action:**

Author: Stockdill, Scott

Notes:

Arrived on location 1:59 9/4/2019.

No sign of contamination or contaminants at the described location. Contact company regarding site cleanup and location.

More follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 9/9/2019 **Status:** Correspondence **No Further Action:**

Author: Stockdill, Scott

Notes:

Emailed Responsible party requesting samples of the spill location and requested confirmation that the water involved was fresh water.

Updated Volumes and Contaminant None at the time of this update

Date: 10/15/2019 **Status:** Correspondence - No Action Required **No Further Action:**

Author: Stockdill, Scott

Notes:

email from responsible party.

"... These are the pin drops of where the samples were taken (Google earth Format "

Full email and attachments in the incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 7/20/2020 **Status:** Inspection - No Action Required **No Further Action:**

Author: Stockdill, Scott

Notes:

Review of incident and the associated documents indicate that the site has minimal impacts off of the well pad. Some elevated samples that can be left to naturally attenuate..

No follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update