## Oil Field Environmental Incident Summary

Incident: 20190905174225 Notice: 9/5/2019 17:42 Occurred: 9/5/2019 16:00

Responsible Party: Badlands Hydrovac

Well Operator: SECURE ENERGY SERVICES USA, LLC

Well Name: SORENSON SWD #1
Field Name: UNION CENTER

**Well File #:** 90250

Facility ID #:

County: MCKENZIE

*Twp Rng Sec Qtr:* 152 96 14 SW SE

**Location Description:** 

Submitted By: Chris Applebee

Received By:

Contact Info: David Martens

5807 FRONT STREET WEST

WILLISTON ND 58801

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Tank Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 10 Barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd:

Risk Evaluation:

Coned off area so drivers would not track the material worse than the spill actually was.

Areal Extent:

Potential Env. Impacts:

None

Action Taken/Planned:

Called the hydrovac company and they are cleaning up the spill with multiple trucks. Put 10 bbls but the amount spilled is unknown and it went down our entrance which is off of the site and is not within the dike.

Wastes Disposal Location:

The Hydrovac company will dispose at the proper facility/Landfill.

Other Agencies Involved:

## **Updates**

Date: 9/6/2019 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: O'Gorman, Brian

Notes:

Release, due to a tank leak was contained on the well site according to the report. NDIC retains

oversight.

Updated Volumes and Contaminant None at the time of this update