

# Oil Field Environmental Incident Summary

**Incident:** 20190916163528      **Notice:** 9/16/2019    16:35    **Occurred:** 9/15/2019    12:00

**Responsible Party:** Oneok Rockies Midstream  
**Well Operator:** ONEOK ROCKIES MIDSTREAM

**Well Name:**

**Field Name:**

**Well File #:**

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 149 92 8

**Location Description:** 47.965317, -102.622465

**Submitted By:** Levi Weltikol

**Received By:**

**Contact Info:** Levi Weltikol  
896 25th St SE  
Sidney MT 59270

**Affected Medium:** Topsoil

**General Land Use:** Pasture

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained:** Yes - On Pipeline ROW

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

<b>Other</b>	20	Gallons
--------------	----	---------

**Oth Rel. Contaminant:** Natural gas condensate

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

No immediate risk

**Areal Extent:**

**Potential Env. Impacts:**

Impacts were isolated to soil around pipeline and immediate surface soils. Impacted materials will be taken to disposal. No environmental impacts are anticipated.

**Action Taken/Planned:**

Pipeline was blown down. Impacted soil was excavated and will be taken to proper disposal. line will be repaired and returned to service.

**Wastes Disposal Location:**

TBD

**Other Agencies Involved:**

## Updates

---

**Date:** 9/17/2019      **Status:** Reviewed - Follow-up Required      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release on pipeline ROW. Follow up is required.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 9/23/2019      **Status:** Inspection - More Follow-up Required      **No Further Action:**

**Author:** Biemiller, Richard

**Notes:**

Arrived on site 1120am on 9/17/2019. It was sunny and in the 70's. Met with environmental consultant for responsible party. Area has been excavated. Samples have been taken at bottom and side walls to delineate. Soil is also being tested to determine if it is acceptable as backfill. Results will be sent to DEQ. More follow up needed.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 3/24/2020      **Status:** Correspondence - More Follow-up Required      **No Further Action:**

**Author:** Suess, Bill

**Notes:**

Contacted the RP regarding sampling results. Awaiting a response.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 3/31/2020      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Suess, Bill

**Notes:**

This incident occurred within the Ft Berthold Reservation. MHA Nation retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update