## **Oil Field Environmental Incident Summary**

								•	
Inc	ident: 2	201910301423	35 <b>N</b>	otice: 10/30/2019	14:23	Occurre	<b>d:</b> 10/30/201	9 1	10:00
Responsible Party:		Continental Resources							
Well Operator:		CONTINENTAL RESOURCES, INC.							
Well Name:		NASHVILLE 5-21H							
Field Name:		CATWALK							
Well File #:		31867							
Facility ID #:									
County:		WILLIAMS							
Twp Rng Sec Qtr:		154 100 21							
Location Description:									
Submitted By:		Tyrell Hanso	on						
Received By:									
Contact Info:		Ben Tarap							
		20 N BroadwayAve.							
			OKLAHOMA CITY OK 73126						
Affected Medium:		Topsoil							
General Land Use:		Cultivated							
Near. Occupied Bldg:									
Nea	arest W	ater Well:							
Type of Incident:			Valve/Piping Connection Leak						
Release Contained:		No							
Reported to NRC:		No							
		Spilled	Units	Recovered	Units		Followup	Units	;
Oil		1	Barrels						
Bri	ne								
Other									
Oth Rel. Contaminant:									
Date Inspected:									
Clean Up Concluded:									
		eport Recd:							
-	k Evalı	lation:							
tops									
Areal Extent:									
200x100 ft. area of stubble field lightly misted									
Potential Env. Impacts:									
tops									
Action Taken/Planned:									
1 1 -	+	الحدم متبدماء است	a alcia alate d			+- /			

Unit was shut down and leak isolated immediately. Off location waste (approx 5 gallons) left for natural attenuation per landowners request.

Wastes Disposal Location:

Other Agencies Involved:

## **Updates**

Date: 10/31/2019 No Further Action: Status: Reviewed - Follow-up Required Author: Crowdus, Kory Notes: Release impacted areas off location. Follow up is required. Updated Volumes and Contaminant None at the time of this update Date: 11/20/2019 No Further Action: Status: Inspection - More Follow-up Required Author: Crowdus, Kory Notes: On location 11/20/2019, at 1:24pm. A workover rig is on location at this time. An inspection will need to be done at a later date. Further follow up is required. No photos taken. Updated Volumes and Contaminant None at the time of this update Date: 3/25/2020 Status: Correspondence - More Follow-up Required No Further Action: Author: Suess, Bill Notes: This site will need to be re-inspected in the spring, when there is no longer a workover rig on location. The RP has been contacted for an update. They will be re-assessing the incident in the spring.

Updated Volumes and Contaminant None at the time of this update

Date: 7/23/2020 Status: Inspection - No Action Required

No Further Action:

Author: Suess, Bill

## Notes:

Inspected the site on 7/21/2020. No adverse environmental impacts associated with this incident were observed. The vegetation appeared healthy and consistent with the surrounding area. No further action is warranted.

Updated Volumes and Contaminant None at the time of this update