

Oil Field Environmental Incident Summary

Incident: 20191106113932 **Notice:** 11/6/2019 11:39 **Occurred:** 11/5/2019 16:00

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: IRWIN 41-25 CENTRAL TANK BATTERY

Field Name: FOREMAN BUTTE

Well File #:

Facility ID #: 236494-01

County: MCKENZIE

Twp Rng Sec Qtr: 150 103 25 NE NE

Location Description: Pad lat/long is 47.7891116, -103.8016823

Submitted By: Brian Wurm

Received By:

Contact Info:
 Brian Wurm
 1700 BROADWAY STE 2300
 DENVER CO 80290

Affected Medium: Topsoil

General Land Use: Cultivated

Near. Occupied Bldg: 0.2 Mile

Nearest Water Well: 0.2 Mile

Type of Incident: Equipment Failure

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels				

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Minimal risk anticipated. The release is stopped and cleanup is in progress.

Areal Extent:

Approximately 570' by 135' at its widest points of light oil mist impact

Potential Env. Impacts:

Minimal environmental impacts anticipated. The release is stopped and cleanup is in progress.

Action Taken/Planned:

The cause of the release is currently being investigated. Impacted material on location will be removed and impacted vegetation off location will be mowed and addressed to landowner satisfaction.

Wastes Disposal Location:

Any impacted material that needs to be removed will be taken to an approved nearby landfill

Other Agencies Involved:

Updates

Date: 11/7/2019 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: Stockdill, Scott

Notes:

According to the incident summary this spill impacted the surrounding area. More follow up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 11/18/2019 **Status:** Inspection - More Follow-up Required

No Further Action:

Author: Schmitt, Bryan

Notes:

Inspection Date: 11/14/2019

Time: 11:00 am CT

Spill occurred between two well pads. Oil impacted soil was observed and it appeared that no cleanup had occurred. Snow covered a portion of the impacted area so it was not possible to estimate the total area impacted by the spill. A hydrocarbon smell was present throughout the spill area. Pictures taken.

Updated Volumes and Contaminant None at the time of this update

Date: 8/12/2020 **Status:** Inspection - No Action Required

No Further Action:

Author: Stockdill, Scott

Notes:

Arrived on location 2:18 8/12/2020.

No sign of impacts or contaminants at the time of inspection.

No follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update