Oil Field Environmental Incident Summary

Incident: 20191111090650 Notice: 11/11/2019 09:06 Occurred: 11/9/2019 21:53

Responsible Party:MARATHON OIL COMPANYWell Operator:MARATHON OIL COMPANY

Well Name: GLADYS USA 21-2H

Field Name: REUNION BAY

Well File #: 18243

Facility ID #:

County: MOUNTRAIL
Twp Rng Sec Qtr: 150 93 2

Location Description:

Submitted By: Ryan Fleeman

Received By:

Contact Info: Ryan Fleeman

3172 HWY 22 N

DICKINSON ND 58601

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak
Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 300 Barrels 300 Barrels 300 barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 12/13/2019
Written Report Recd: 2/28/2020

Risk Evaluation:

None. Released fluids contained onsite and will be cleaned up.

Areal Extent:

Potential Env. Impacts:

None. Released fluids contained onsite and will be cleaned up.

Action Taken/Planned:

Upon inspection the fitting connection was a 4-Inch aluminum nipple. We will no longer have any aluminum fittings on the tanks. This will also be added to our tank audit procedures.

Wastes Disposal Location:

Other Agencies Involved:

MHA Energy

Updates

Date: 11/12/2019 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: O'Gorman, Brian

Notes:

Release is within MHA Nation. Report forwarded to BIA, MHA Environmental and EPA.

Updated Volumes and Contaminant None at the time of this update