Oil Field Environmental Incident Summary

Incident: 20200207120947 Notice: 2/7/2020 12:09 Occurred: 2/6/2020 13:30

Responsible Party: CONTINENTAL RESOURCES, INC.
Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: SPOONER 1-11H

Field Name: SADLER Well File #: 17650

Facility ID #:

County: DIVIDE

Twp Rng Sec Qtr: 161 95 11

Location Description: 25' x 10' west of the location

Submitted By: Nate Sem

Received By:

Contact Info: Jesse Puckett

PO Box 268870

Oklahoma City OK 73126

Affected Medium: Topsoil

General Land Use: Cultivated

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 1 Gallons 1 Gallons

Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

None

Areal Extent:

25' x 10' west of the location

Potential Env. Impacts:

lightly misted oil on top of snow

Action Taken/Planned:

Contaminated snow on location was bladed. Affected snow off location was scooped up (per landowner's request).

Wastes Disposal Location:

TBD

Other Agencies Involved:

2/6/20 3:20 pm - called NDIC (Jonathan Rumppe)

2/7/20 8:41 am - called NDDoH (B. Suess) - left voicemail

Updates

Date: 2/7/2020 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: Lund, Dylan

Notes:

According to the incident report, the release misted oil off the well pad. Follow-up necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 2/18/2020 Status: Inspection - No Action Required No Further Action: ✓

Author: Stockdill, Scott

Notes:

Arrived on location 3:12 2/12/2020.

No sign of contamination or contaminants off of location. Impacted snow stockpiled on location.

No follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update