

Oil Field Environmental Incident Summary

Incident: 20200211162229 **Notice:** 2/11/2020 16:22 **Occurred:** 2/11/2020 11:30

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: ECKERT 7 1

Field Name: INDIAN HILL

Well File #: 10685

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 152 101 7

Location Description:

Submitted By: Beki Sample

Received By:

Contact Info: Beki Sample
4901 LBJ FREEWAY, STE 300
DALLAS TX 75244

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 2550 Feet

Nearest Water Well: 1026 Feet

Type of Incident: Treater Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	40	Gallons		
Brine	1	Barrels	35	Gallons		

Other

Oth Rel. Contaminant: N/A

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

No risks

Areal Extent:

N/A

Potential Env. Impacts:

No risks

Action Taken/Planned:

A vac truck was dispatched to recover the lost emulsion. There will be a hot oil truck and a vac truck onsite tomorrow to wash down location and recover any other oil and/or waste. A roustabout crew will pull the fire tube tomorrow also.

Wastes Disposal Location:

Hoehn Disposal

Other Agencies Involved:

Updates

Date: 2/11/2020

Status: Reviewed - Assigned to Other Agency

No Further Action:

Author: Suess, Bill

Notes:

Incident was contained on an E & P exempt facility. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update