

# *Oil Field Environmental Incident Summary*

**Incident:** 20200211205922      **Notice:** 2/11/2020    20:59    **Occurred:** 2/11/2020    15:00

**Responsible Party:** HENRY HILL OIL SERVICES, LLC

**Well Operator:** HENRY HILL OIL SERVICES, LLC

**Well Name:** NORTH DICKINSON SWD 1

**Field Name:** ST. ANTHONY

**Well File #:** 6224

**Facility ID #:**

**County:** DUNN

**Twp Rng Sec Qtr:** 141 96 11 NE NE

**Location Description:**

**Submitted By:** Dustin Mahoney

**Received By:**

**Contact Info:** Jake Burton  
120 26th St East  
SUITE 200  
WILLISTON ND 58801-2404

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	7	Barrels	7	Barrels		

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

Salt water exposure.

**Areal Extent:**

**Potential Env. Impacts:**

Soil within the primary containment area.

**Action Taken/Planned:**

Upon discovery valve was closed. Robby Ridl truck sucked up the water and pumped back into the system on site. Containment will be washed and cleaned up.

**Wastes Disposal Location:**

Pumped back into the tanks on site.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 2/12/2020      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Suess, Bill

**Notes:**

Incident was fully contained on an E & P exempt facility. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update