# **Oil Field Environmental Incident Summary**

Incident: 202002151218	02 Notice: 2/15/202	0 12:18	Occurred: 2/14/2020	) 16:00	
Responsible Party:	XTO ENERGY INC				
Well Operator:	XTO ENERGY INC				
Well Name:	SONYA 11X-18 CTB				
Field Name:	HOFFLUND				
Well File #:					
Facility ID #:	232311-01				
County:	WILLIAMS				
Twp Rng Sec Qtr:	154 95 18 LO 1				
Location Description:					
Submitted By:	Kaylan Dirkx				
Received By:					
Contact Info:	Kaylan Dirkx				
	110 WEST 7TH STREET				
	FORT WORTH TX 76102	2			
Affected Medium:	Well/Facility Soil				
General Land Use:	Well/Facility Site				
Near. Occupied Bldg:					
Nearest Water Well:					
Type of Incident:	Other				
Release Contained:	No				
Reported to NRC:	No				
Spilled	Units Recover	red Units	Followup	Units	
Oil					
Brine					
<b>Other</b> 20	Gallons				
Oth Rel. Contaminant:	H2S Scavenger				
Date Inspected:					
Clean Up Concluded:					
Written Report Recd:					
Risk Evaluation:					
Minimal fluid released and release was quickly isolated.					
Areal Extent:					
Approximately 3 gallons off pad to the SW (40' x 40').					
Potential Env. Impacts:					
Minimal fluid released (17 gallons on pad and 3 gallons off pad onto snow)					

### Action Taken/Planned:

Release was isolated and equipment settings are being inspected. JMAC will be removing the off pad snow and disposing of it. On pad cleanup will start next week.

## Wastes Disposal Location:

Off pad snow will be disposed of at IHD. Additional clean up details will be captured in the NDIC Follow up Report

### **Other Agencies Involved:**

# Updates

Date: 2/18/2020 Status: Reviewed - Follow-up Required   Author: Suess, Bill	No Further Action: ✔			
<i>Notes:</i> Incident was not fully contained, follow-up is needed.				
Updated Volumes and Contaminant None at the time of this update				
Date: 3/6/2020 Status: Inspection - More Follow-up Required	No Further Action: 🗸			
Author: Stockdill, Scott				
Notes:				
Arrived on location 12:51 3/3/2020.				
No sign of contamination or contaminants at the time of inspection.				
Contact company to ensure proper location.				
More follow-up is necessary.				

Updated Volumes and Contaminant None at the time of this update