

Oil Field Environmental Incident Summary

Incident: 20200215170716 **Notice:** 2/15/2020 17:07 **Occurred:** 2/14/2020 08:30

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: RS-BEAN-156-91- 3229H-1

Field Name: ROSS

Well File #: 18059

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 156 91 32

Location Description:

Submitted By: Troy Brunsell

Received By:

Contact Info: Benji Foss
3015 16TH ST SW
MINOT ND 58701

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 0.1 Mile

Nearest Water Well: 0.1 Mile

Type of Incident: Tank Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	35	Barrels	35	Barrels		

Oth Rel. Contaminant: Emulsion / Freshwater

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

No immediate risk to report at this time, released fluid froze overnight and contained on location.

Areal Extent:

Potential Env. Impacts:

Emulsion / Fresh Water released from the frac tank was frozen around the tank / valve on location.

Action Taken/Planned:

Cleanup is underway to recover the frozen ice around the frac tank and valve.

Wastes Disposal Location:

An approved waste facility

Other Agencies Involved:

Updates

Date: 2/18/2020 **Status:** Reviewed - Assigned to Other Agency

No Further Action:

Author: Suess, Bill

Notes:

Incident was contained on a well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update