

Oil Field Environmental Incident Summary

Incident: 20200216184751 **Notice:** 2/16/2020 18:47 **Occurred:** 2/16/2020 06:45

Responsible Party: Tradestar Trucking
Well Operator: HENRY HILL OIL SERVICES, LLC
Well Name: NELSON 1 SWD
Field Name: LONE TREE LAKE
Well File #: 90404
Facility ID #:
County: WILLIAMS
Twp Rng Sec Qtr: 157 99 9 NE SE
Location Description:
Submitted By: Dustin Mahoney
Received By:
Contact Info: David Hopper
Williston
WILLISTON ND 58801-2404

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other
Release Contained: Yes - On Facility Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	35	Gallons	35	Gallons		

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Soil on site.

Areal Extent:

Potential Env. Impacts:

Soil on site.

Action Taken/Planned:

Truck driver immediately sucked up the water, contaminated soil was removed and new soil brought in.

Wastes Disposal Location:

Secure

Other Agencies Involved:

Updates

Date: 2/18/2020

Status: Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: Suess, Bill

Notes:

Incident was contained on an E&P exempt facility. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update