

Oil Field Environmental Incident Summary

Incident: 20200216184756 **Notice:** 2/16/2020 18:47 **Occurred:** 2/16/2020 06:45

Responsible Party: Tradestar Trucking
Well Operator: HENRY HILL OIL SERVICES, LLC
Well Name: NELSON 1 SWD
Field Name: LONE TREE LAKE
Well File #: 90404
Facility ID #:
County: WILLIAMS
Twp Rng Sec Qtr: 157 99 9 NE SE
Location Description:
Submitted By: Dustin Mahoney
Received By:
Contact Info: David Hopper

Williston
 WILLISTON ND 58801-2404

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Other
Release Contained: Yes - On Facility Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	35	Gallons	35	Gallons		
Other						

Oth Rel. Contaminant:
Date Inspected:
Clean Up Concluded:
Written Report Recd:
Risk Evaluation:

Soil on site.

Areal Extent:
Potential Env. Impacts:

Soil on site.

Action Taken/Planned:
 Truck driver immediately sucked up the water, contaminated soil was removed and new soil brought in.

Wastes Disposal Location:
 Secure

Other Agencies Involved: