

# *Oil Field Environmental Incident Summary*

**Incident:** 20200730184908      **Notice:** 7/30/2020    18:49    **Occurred:** 7/30/2020    16:00

**Responsible Party:** HENRY HILL OIL SERVICES, LLC

**Well Operator:** HENRY HILL OIL SERVICES, LLC

**Well Name:** MASTON 1 SWD

**Field Name:** BANKS

**Well File #:** 90385

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 152 98 9

**Location Description:**

**Submitted By:** Dustin Mahoney

**Received By:**

**Contact Info:** Jake Burton  
120 26th St E  
SUITE 200  
WILLISTON ND 58801-2404

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

<b>Brine</b>	5	Barrels	5	Barrels		
--------------	---	---------	---	---------	--	--

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

Soil on site

**Areal Extent:**

**Potential Env. Impacts:**

Soil on site

**Action Taken/Planned:**

Leak was isolated, water that came out of the pump house was sucked up, soil to be washed with a super vac truck. Replaced check valve.

**Wastes Disposal Location:**

Pumped back into the system.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 7/31/2020      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

**Updated Volumes and Contaminant**    None at the time of this update