

Oil Field Environmental Incident Summary

Incident: 20201228064517 **Notice:** 12/28/2020 06:45 **Occurred:** 12/27/2020 22:30

Responsible Party: HENRY HILL OIL SERVICES, LLC

Well Operator: HENRY HILL OIL SERVICES, LLC

Well Name: LUNDEEN 1 SWD

Field Name: BANKS

Well File #: 90456

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 152 98 26

Location Description:

Submitted By: Jess McGinley

Received By:

Contact Info: Jess McGinley
120 26th St E
SUITE 200
WILLISTON ND 58801-2404

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 1 Mile

Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	5	Gallons	5	Gallons		

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

low. water contained around pot

Areal Extent:

20 sq feet

Potential Env. Impacts:

low. small amount and vac'd up quickly

Action Taken/Planned:

reinforce following procedure. Double check location of work area

Wastes Disposal Location:

on location and in contamination bins

Other Agencies Involved:

Updates

Date: 12/28/2020 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Lund, Dylan

Notes:

According to the incident report, the release was contained to the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update