

Oil Field Environmental Incident Summary

Incident: 20201231132054 **Notice:** 12/31/2020 13:20 **Occurred:** 12/31/2020 11:20

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: MARSHALL 1-13H

Field Name: LITTLE KNIFE

Well File #: 20256

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 145 97 13

Location Description: Lightly misted an area approximately 15' x 15' in a pasture off the SE corner of location.

Submitted By: NATE STANHOPE

Received By:

Contact Info:
 CHANSY WOLFF
 PO BOX 268870
 OKLAHOMA CITY OK 73126

Affected Medium: Topsoil

General Land Use: Pasture

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Gallons				

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

N/A

Areal Extent:

15' x 15' area of pasture off the SE corner lightly misted.

Potential Env. Impacts:

Vegetation and topsoil

Action Taken/Planned:

The misted area on location will be back dragged and will discuss with the landowner cleanup options in the pasture.

Wastes Disposal Location:

TBD

Other Agencies Involved:

Updates

Date: 12/31/2020 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: Suess, Bill

Notes:

According to the incident report, this spill was not confined to the well pad. Follow-up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 1/6/2021 **Status:** Inspection - Vegetation Check **No Further Action:**

Author: Suess, Bill

Notes:

Inspected the site on 1/4/2021. At the time of the inspection, there was minor staining of the vegetation off the SE corner of the well pad near the flare. The impact area was approximately 15 feet by 15 feet. Met with the RP rep and was informed that the landowner did not want the area excavated. The vegetation is too short to mow so the RP will rake the area then allow for natural attenuation. The site should be inspected in the spring of 2021 to assure attenuation and proper revegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 5/3/2021 **Status:** Inspection - Vegetation Check **No Further Action:**

Author: Crowdus, Kory

Notes:

On location 5/3/2021, at 5:32pm. Light oil staining off location to the Southeast. Area is approximately 50 x 30 ft. Natural attenuation would appear to be the best solution for this incident. Further follow-up to check on vegetation health is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 11/3/2021 **Status:** Inspection - Vegetation Check **No Further Action:**

Author: Suess, Bill

Notes:

This incident has been re-assigned to D. Kaiser.

Updated Volumes and Contaminant None at the time of this update

Date: 7/14/2022 **Status:** Inspection - No Action Required **No Further Action:**

Author: Suess, Bill

Notes:

Inspected the site on 7/12/2022. The vegetation appears healthy and consistent with the surrounding area. No adverse environmental conditions associated with this incident were observed. No further action is warranted.

Updated Volumes and Contaminant None at the time of this update