

# General Environmental Incident Summary

**Incident:** 10538

**Notice:** 7/22/2020 1825

**Occurred:** 7/21/2020 1200

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** Minnesota Power Bison Wind Energy Center

**County:** Morton

**Twp Rng Sec Qtr:** 141 86 4

**Lat Long + Method:** 46.97997 -101.55470 Navigation quality GPS

**Location Description:** Bison Wind Energy Center; 5198 30th Street, New Salem, ND 58563; From I-94 take exit 120, head 8 miles north then 1 mile east

**Submitted By Info:** Drew Janke  
Minnesota Power  
30 W Superior Street  
Duluth MN 55802

**Received By Info:**

**Contact Info:**

5198 30th Street  
New Salem ND

**Affected Medium:** 09 - other

**Near. Occupied Bldg:** 1.1 Miles

**Type of Incident:** Leak from cylinder

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** Hydraulic Fluid

**Volume of Release:** 0.25 gallons

**Duration of Release:**

**Agriculture Related:** No

**EPA Extremely  
Hazardous Substance:** No

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

Leaked from hydraulic fluid cylinder stored outside on concrete apron.

**Risk Evaluation:**

No immediate risk.

**Potential Env. Impacts:**

No potential environmental impacts.

**Action Taken/Planned:**

Spill contained itself to concrete apron. Cleaned up with floor dry.

**Wastes Disposal Location:**

Clean Harbors Sawyer Landfill

**Other Agencies Involved:**

## **Updates**

---

**Date:** 7/24/2020      **Status:** Reviewed - No Action Required

**Author:** Suess, Bill

**Notes:**

According to the incident report, this spill involved less than a gallon of hydraulic oil that was confined to a concrete apron. No follow-up is needed.

**Updated Volume:** None at the time of this update