

Updates

Date: 12/1/2020 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to the incident report, there was a release of 1500 gallons of petroleum contact water. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 12/14/2020 **Status:** Correspondence - More Follow-up Required

Author: DeVries, Taylor

Notes:

Received confirmation soil sample results from the responsible party. Benzene was non-detect. Responsible party had some further questions.

Soil sample results can be found in the report folder.

Updated Volume: None at the time of this update

Date: 12/14/2020 **Status:** Correspondence - No Action Required

Author: DeVries, Taylor

Notes:

Responded to a few questions Magellan had about reporting limits. With the soil sample results, there is no further follow-up needed with this site at this time.

Updated Volume: None at the time of this update

Date: 12/14/2020 **Status:** Correspondence - No Action Required

Author: DeVries, Taylor

Notes:

Taylor DeVries sent a No Further Action letter dated December 14, 2020.

Updated Volume: None at the time of this update