

General Environmental Incident Summary

Incident: 10628

Notice: 12/11/2020

Occurred: 12/10/2020 1842

DEM Incident No:

No Further Action:

Responsible Party: Marathon Oil

County: Mountrail

Twp Rng Sec Qtr: 150 93 5 NW NE

Lat Long + Method: 47.84671 -102.60940 Interpolation from map

Location Description: Joba USA 31-5H. Take Sanish Hwy south on the peninsula (east of New Town). Turn west on 30th St and pad is located on south side of road.

Submitted By Info: Ryan Fleeman
3172 HWY 22 N
Dickinson ND 58601

Received By Info:

Contact Info: Ryan Fleeman
3172 HWY 22 N
Dickinson ND 58601

Affected Medium: 03 - soil

Near. Occupied Bldg: 0.7 Miles

Type of Incident: Water filtration system overflowed for onsite housing

Release Contained: Yes

Reported to NRC: No

Contaminant: Sewage

Volume of Release: 38 gallons

Duration of Release: 15 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

When inspecting onsite housing, it was observed that one of the sewage reservoirs for the water filtration system was overflowing onto the engineered pad.

Risk Evaluation:

None. Spill will be cleaned up by contractor providing onsite housing.

Potential Env. Impacts:

Contained on pad lined with earthen perimeter berms.

Action Taken/Planned:

The service provider was dispatched to location, and it was determined that a tripped breaker caused the power to the transfer pump to be shut off and allowed the tank to overflow from a piping port.

Wastes Disposal Location:

Other Agencies Involved:

MHA Energy

Updates

Date: 12/11/2020 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Notes:

According to the incident summary this release occurred within the MHA Nations boundaries.
Forward to BIA/Tribal Authorities.

Updated Volume: None at the time of this update