

General Environmental Incident Summary

Incident: 5296

Notice: 12/21/2016 1754

Occurred: 12/21/2016 0900

DEM Incident No:

No Further Action:

Responsible Party: Tesoro High Plains Pipeline

County: McKenzie

Twp Rng Sec Qtr: 151 95 19 SW SE

Lat Long + Method: 47.87718 -102.88320 Interpolation from map

Location Description: From Keene North Dakota travel 3.5 miles south on hwy 23 to County Road 14. At County road 14 travel east 2.7 miles to Tesoro's Blue Buttes Crude Oil Station.

Submitted By Info: Mark Glaser
Tesoro - Employee
2972 108S Ave SW
Dickinson ND 58601

Received By Info:

Contact Info: Mark Glaser
2972 108S Ave SW
Dickinson ND 58601

Affected Medium: 03 - soil

Near. Occupied Bldg: 1175 Feet

Type of Incident: Tank Leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: crude oil

Volume of Release: 2 barrels

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

A mechanical seal on the mixer shaft failed causing a drip.

Risk Evaluation:

None

Potential Env. Impacts:

Impacts to soil and snow. No impacts to surface or ground water.

Action Taken/Planned:

Oil tank was drained and seal was repaired. Soil and snow impacted by crude oil is being removed to disposal.

Wastes Disposal Location:

To a permitted and approved waste disposal facility such as R360.

Other Agencies Involved:

Updates

Date: 12/22/2016 **Status:** Reviewed - Follow-up Required

Author: Schiermeister, Robin

Notes:

Release impacted the snow and air. Further follow-up is necessary.

Updated Volume: None at the time of this update

Date: 1/11/2017 **Status:** Inspection

Author: Striebel, Ivana

Notes:

Met with company representative, JR Pinto, who escorted me to the area where the spill occurred. Spill happened on the back side of the large white tank at the back of the tank farm. Contractors have already cleaned up the impacted snow. Three loads, 4.01 and 6.24 tons of impacted snow, and 60 bbls of liquids (snow and oil) have been removed from site. Site is buried under new snow, which made viewing any remaining contamination impossible. Tank still has oil on it and will be cleaned once weather conditions allow for it. An inspection of the site in spring 2017 is needed to confirm complete cleanup. Further follow-up needed.

Updated Volume: None at the time of this update

Date: 11/29/2017 **Status:** Correspondence

Author: Martin, Russell

Notes:

Received closure report on incident as part of a larger information collection on all currently open Tesoro (now Andeavor) incidents. Report for this incident indicates cleanup is complete. Based on report, no further follow-up required at this time.

Updated Volume: None at the time of this update