

General Environmental Incident Summary

Incident: 5327

Notice: 3/1/2017

Occurred: 3/1/2017

DEM Incident No:

No Further Action:

Responsible Party: Otter Tail Power Company

County: Mercer

Twp Rng Sec Qtr: 143 88 10

Lat Long + Method: 47.22138 -101.81580 Interpolation from map

Location Description: 6240 13th Street SW
Beulah, ND

Submitted By Info: Josh Hollen
Otter Tail Power Company
215 S Cascade St
PO Box 496
Fergus Falls MN 56538-0496

Received By Info:

Contact Info:

215 S. Cascade Street
Fergus Falls MN

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Investigating a fuel oil leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Fuel Oil

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Unknown. Plant staff are currently investigating this release.

Risk Evaluation:

The immediate risk is believed to be very low. There are no signs of free product and no vapors present.

Potential Env. Impacts:

Unknown at this time. Soil is likely impacted. Risk to surface water is believed to be low due to the lack of free product.

Action Taken/Planned:

Plant staff are currently investigating this release. There is no visible free product on the property.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 3/1/2017 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

Received a call from Otter Tail Power Company about a possible leak of fuel oil. Further investigation and follow-up with the company is being conducted.

Updated Volume: None at the time of this update

Date: 8/3/2017 **Status:** Correspondence

Author: DeVries, Taylor

Notes:

The fuel oil line that failed its pressure test is being decommissioned. New epoxy coated steel piping is going to be put into place, next to the old capped pipe. No further action required on this spill report. Otter Tail Power Company will fill out a new spill report if fuel oil is found while installing new pipelines.

Updated Volume: None at the time of this update

Date: 8/3/2017 **Status:** Correspondence

Author: DeVries, Taylor

Notes:

Taylor Souder sent a No Further Action letter dated August 3, 2017.

Updated Volume: None at the time of this update

Date: 9/26/2017 **Status:** Correspondence

Author: DeVries, Taylor

Notes:

Spoke with Otter Tail Power Company today and was told that fuel oil impacts were found while installing a new fuel oil pipeline near the pump house of the Coyote Station. Awaiting documentation of soil sample results. Re-opening this incident.

Updated Volume: None at the time of this update

Date: 11/21/2018 **Status:** Reviewed - Assigned to NDDEQ Division

Author: Striebel, Ivana

Notes:

11/21/2018 - This release will be handled by the Solid Waste Program. Any questions or concerns should be directed to Hristo Papalichev, 701-328-5166.

Updated Volume: None at the time of this update