

General Environmental Incident Summary

Incident: 5336 **Notice:** 3/8/2017 1515 **Occurred:** 3/8/2017 1340

DEM Incident No:

No Further Action: ☒

Responsible Party: Tesoro Dickinson Refinery

County: Stark

Twp Rng Sec Qtr: 139 97 15

Lat Long + Method: 46.85460 -102.91450 Interpolation from map

Location Description: Tesoro Dickinson Refinery

Submitted By Info: Riley Lealos
Tesoro - Environmental Specialist
3815 116th Ave SW
Dickinson ND 58601

Received By Info:

Contact Info: Riley Lealos
3815 116th AVE SW
Dickinson ND 58601

Affected Medium: 03 - soil

Near. Occupied Bldg: 0.5 Miles

Type of Incident: 1/4" tube leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Bleach

Volume of Release: 2 gallons

Duration of Release: 2 hours

Agriculture Related: No

**EPA Extremely
Hazardous Substance:** No

Number of Fatalities:

Number of Injuries:

Cause of Incident:

During operator inspection rounds operator noticed dripping from a 1/4" bleach injection line just outside of facility cooling water tower. Operator isolated pump and notified Environmental.

Risk Evaluation:

Low risk

Potential Env. Impacts:

Low environmental impact. 6' x 6' area of soil to be excavated.

Action Taken/Planned:

Pump isolated, soil is in the process of being excavated, effected area was 6' x 6'.

Wastes Disposal Location:

Disposal via Clean Harbors

Other Agencies Involved:

Updates

Date: 3/8/2017 **Status:** Reviewed - No Action Required

Author: O'Gorman, Brian

Notes:

According to the report, 2 gallons of bleach leaked onto soils outside of the facility cooling water tower. Report also states that area will be excavated and materials disposed of at the Clean Harbors facility. No further follow-up needed at this time.

Updated Volume: None at the time of this update