

# General Environmental Incident Summary

**Incident:** 5411                                  **Notice:** 5/24/2017    1620    **Occurred:** 5/24/2017    0900

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** Plains Marketing

**County:** Bowman

**Twp Rng Sec Qtr:** 130 104 14 NW

**Lat Long + Method:** 46.08784 -103.65960 Navigation quality GPS

**Location Description:** 8 miles south of Rhame, ND.

**Submitted By Info:** Daniel Holli  
Plains Marketing  
PO Box 708  
Belfield ND 58622

**Received By Info:**

**Contact Info:** Daniel Holli  
P.O. Box 708  
Belfield ND 58622

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 0.25 Miles

**Type of Incident:** hose leak

**Release Contained:** Yes

**Reported to NRC:** No

**Contaminant:** crude oil

**Volume of Release:** 20 gallons

**Duration of Release:** 5 minutes

**Agriculture Related:** No

**EPA Extremely  
Hazardous Substance:** No

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

Hose leak on vacuum truck

**Risk Evaluation:**

none

**Potential Env. Impacts:**

soil

**Action Taken/Planned:**

Excavate contaminated soil for disposal

**Wastes Disposal Location:**

Chimney Butte landfill

**Other Agencies Involved:**

## **Updates**

---

**Date:** 5/30/2017      **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Notes:**

According to the report, 20 gallons of crude oil impacted soils in the area. Further follow-up needed.

**Updated Volume:** None at the time of this update

---

**Date:** 7/18/2017      **Status:** Inspection

**Author:** Schmitt, Bryan

**Notes:**

Time: 14:00 MST, Temp: 74 F

Spoke to a Plains Marketing employee upon arriving. He said the spill occurred on the pad near the truck hookups and the impacted soil was moved to an area on the northwest side of the property. The contaminated soil was sitting on a tarp and oil staining was evident.

**Updated Volume:** None at the time of this update

---

**Date:** 8/1/2018      **Status:** Inspection

**Author:** O'Gorman, Brian

**Notes:**

Arrived on location at 14:10. 75 degrees F, Southeast wind 5-10 mph, Sunny. Observed the site and took photos. Did not notice any petroleum stained soils near the loading/unloading areas or any of the gravel surface. A pile of scoria and dirt was near the northwest corner of the pad. The pile did not appear to be impacted soil/scoria. Left a message with the company (Bridger Pipeline) to call me back as to the composition of the pile on-site. More follow-up needed. Photos added to the incident folder.

**Updated Volume:** None at the time of this update

---

**Date:** 8/7/2018      **Status:** Correspondence

**Author:** O'Gorman, Brian

**Notes:**

Received a return phone call from a Bridger Pipeline representative at 13:00, answering the question regarding the pile of rock and soil on the loading area. He confirmed that the pile is from some grading they had done inside the fence and it was not contaminated soil/rock. They plan on moving the pile in the near future. No further follow-up needed at this time.

**Updated Volume:** None at the time of this update