# **General Environmental Incident Summary**

		· · · · · · · · · · · · · · · · · · ·
Incident: 5412	Notice: 5/24/2017	<b>Occurred:</b> 5/24/2017 0824
DEM Incident No:		No Further Action: 🗸
Responsible Party:	Albaugh Enterprises LLC	
County:	McKenzie	
Twp Rng Sec Qtr:	149 99 3	
Lat Long + Method:	47.74778 -103.33110	Interpolation from map
Location Description:		ke Hwy 85 to 23rd St NW. Head west on 23rd y 2.15 miles to location on northside of CR 30
Submitted By Info:	Jennie Nay	
	5036 Jackson St	
	Williston ND 58801	
Received By Info:		
Contact Info:	Channing Ledford	
	5036 Jackson Street	
	Williston ND 58801	
Affected Medium:	03 - soil	
Near. Occupied Bldg:		
Type of Incident:	Vehicle Accident	
Release Contained:	Yes	
Reported to NRC:	Unknown	
Contaminant:	70/30 blended diesel fluid	
Volume of Release:	10 gallons	
Duration of Release:	4 hours	
Agriculture Related:	No	
EPA Extremely Hazardous Substance:	Unknown	
Number of Fatalities:	0	
Number of Injuries:	0	
Cause of Incident:		

#### Cause of Incident:

Truck with sidedump was unloading at jobsite off CR 30. During unloading process the truck and trailer tipped over onto its side and punctured fuel cell which allowed diesel fuel to leak out onto topsoil pile.

## Risk Evaluation:

Harmful vapors if inhaled. Potential flammable vapors.

## Potential Env. Impacts:

Spills may infiltrate subsurface soil and groundwater.

### Action Taken/Planned:

Alerted police department. Contacted McKenzie County Health Department regarding spill who sent out an investigator to spill site. Diesel leaked onto fresh topsoil that had been piled and just hauled to CR 30 jobsite. Soil was loaded into one dump truck and 2 sidedumps and taken to Gibson Landfill

#### Wastes Disposal Location:

Gibson Landfill in Williston ND

#### **Other Agencies Involved:**

Local Law Enforcement, Local Emergency Manager

# **Updates**

Date: 5/30/2017 Status: Reviewed - Follow-up Required

Author: O'Gorman, Brian

# Notes:

According to the report, 10 gallons of diesel fuel was released onto soil surface. Further follow-up needed.

**Updated Volume:** None at the time of this update

*Date:* 6/26/2017 *Status:* Correspondence

Author: Martin, Russell

Notes:

Received waste manifest for the incident.

Updated Volume: None at the time of this update

Date: 6/29/2017 Status: Inspection

Author: Martin, Russell

Notes:

6/27/2017 at 15:27, on location. The construction crew, who were onsite rebuilding the bridge, confirmed location of incident, and McKenzie County Emergency Manager confirmed also, as she was onsite to observe the cleanup. No visible staining, site is dug up and partially incorporated into the roadway. No further follow-up required at this time.

Updated Volume: None at the time of this update