

General Environmental Incident Summary

Incident: 5461

Notice: 7/17/2017

Occurred: 7/13/2017 1200

DEM Incident No:

No Further Action:

Responsible Party: CHS Transportation

County: Mountrail

Twp Rng Sec Qtr: 152 88 3

Lat Long + Method: 48.00714 -101.92970 Interpolation from map

Location Description: Dakota Gold Rail yard, 6286 41st St NW, Plaza, ND.

Submitted By Info: Charlie Johnson
Cenex Harvest States
3290 140th St E
Rosemount MN 55068-2807

Received By Info:

Contact Info:

4115 27th Ave North
Grand Forks ND

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Broken hydraulic hose on truck

Release Contained: Yes

Reported to NRC: No

Contaminant: Hydraulic oil

Volume of Release: 1 gallons

Duration of Release: 1 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Hydraulic hose broke on truck while unloading causing a 1 gallon spill on gravel.

Risk Evaluation:

Minor risk, motor type oil. Affected soil was cleaned up.

Potential Env. Impacts:

Minor impact to soil (dirt road). Soil was cleaned up.

Action Taken/Planned:

Contaminated dirt was cleaned up with a shovel and taken to the CHS shop in Minot and stored in drum for later disposal by Safety Kleen.

Wastes Disposal Location:

Drum will be picked up and remediated by Safety Kleen.

Other Agencies Involved:

Updates

Date: 7/17/2017 **Status:** Correspondence

Author: Schiermeister, Robin

Notes:

Incident was filed with incorrect Section. The railyard is in Section 3. It has been changed in the database.

Release, due to a broken hydraulic hose, was properly cleaned up with the contaminated soil properly disposed of. No further follow-up is necessary at this time.

Updated Volume: None at the time of this update