

# General Environmental Incident Summary

**Incident:** 5514

**Notice:** 9/14/2017

**Occurred:** 9/14/2017 1400

**DEM Incident No:**

**No Further Action:** ☒

**Responsible Party:** Johnson Bros

**County:** McKenzie

**Twp Rng Sec Qtr:** 153 101 6 NE

**Lat Long + Method:** 48.10784 -103.71600 Interpolation from map

**Location Description:** Missouri River, HWY 85 Bridge construction project -2 miles south of Hwy 2 junction

**Submitted By Info:** Gaurav Patil  
Johnson Bros  
4812 Southview Ave  
Williston ND 58801

**Received By Info:**

**Contact Info:**

4812 southview avenue  
williston ND 58801

**Affected Medium:** 02 - water

**Near. Occupied Bldg:** 1 Miles

**Type of Incident:** Equipment failure

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** Non-hazardous ,biodegradable hydraulic oil

**Volume of Release:** 0.25 gallons

**Duration of Release:** 1 minutes

**Agriculture Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

Hose on vibratory hammer broke.

**Risk Evaluation:**

The non hazardous oil was contained and disposed of safely.

**Potential Env. Impacts:**

No environmental impacts anticipated

**Action Taken/Planned:**

oil absorbent boom was placed to absorb the oil.The hose that failed was replaced immediately.

**Wastes Disposal Location:**

The recovered waste was disposed of in our oil recycling dumpster located off the project site in our office trailer yard.

**Other Agencies Involved:**

## ***Updates***

---

***Date:*** 9/14/2017      ***Status:*** Reviewed - No Action Required

***Author:*** Crowdus, Kory

***Notes:***

No on-site inspection is necessary as this spill is being monitored through the permit administered by the NDDoH Division of Water Quality.

***Updated Volume:*** None at the time of this update